

<b>Safety Recommendation Number:</b>	IRLD2015008
<b>AAIU Event Reference:</b>	IRL00914111
<b>AAIU Report Number:</b>	2015-013
<b>Date of Publication of Safety Recommendation:</b>	06/07/2015
<b>Safety Recommendation Status:</b>	Implemented, closed

**Safety Recommendation:**

Jabiru Aircraft Pty Ltd should include a warning in the Instruction and Maintenance Manuals for the Jabiru 2200 engine and similar Jabiru engine types, highlighting that if oil cooler hoses are installed with oil on the hose fittings or, with oil on the inside of the hose in the vicinity of the fittings, hose security may be adversely affected.

**Response:**

Jabiru responded to the AAIU by Email dated 01 October 2015 advising that the Engine Installation Manuals and Maintenance Manual for the Jabiru 2200 and 3300 have been amended to include the warning as recommended and that the following text has been added -

"Note: If oil cooler hoses are installed with oil on the hose fittings or, with oil on the inside of the hose in the vicinity of the fittings, hose security may be adversely affected."

**AAIU Comment:**

The AAIU considers the status of this Safety Recommendation as "Implemented, Closed"