

<b>Safety Recommendation Number:</b>	IRLD2015009
<b>AAIU Event Reference:</b>	IRL00914111
<b>AAIU Report Number:</b>	2015-013
<b>Date of Publication of Safety Recommendation:</b>	06/07/2015
<b>Safety Recommendation Status:</b>	Closed

**Safety Recommendation:**

Jabiru Aircraft Pty Ltd should, with the aid of a suitable publication, promulgate de-identified details of the subject event to users of its engines.

**Response:**

Jabiru responded to the AAIU by Email dated 01 October 2015 advising that Jabiru Service Letter JSL018 was published on 1 October 2015. This Service Letter contains de-identified details of the subject event and highlights the precautions to be considered for oil cooler hose selection, installation and security . Service Letter JSL018 is available on the Jabiru website at the following link

[http://jabiru.net.au/images/JSL018-1\\_Oil\\_Cooler\\_Hoses.pdf](http://jabiru.net.au/images/JSL018-1_Oil_Cooler_Hoses.pdf)

**AAIU Comment:**

The AAIU considers the status of this recommendation as "Accepted /Closed"