

Safety Recommendation Number:	IRLD2016008
AAIU Event Reference:	IRL00913099
AAIU Report Number:	2016-007
Date of Publication of Safety Recommendation:	10/05/2016
Safety Recommendation Status:	Implemented, closed

Safety Recommendation:

The Boeing Aircraft Company should review the status of the Boeing Fleet Team Digest relating to erroneous airspeed with a view to reissuing the guidance material.

Response:

31 August 2016:

Boeing Aircraft Company responded to the AAIU by letter advising as follows;

"Boeing has reviewed and twice revised FTD Article 757-FTD-34-10005 subsequent to the 20 October 2013 event, and is satisfied with the content of the article as it relates to erroneous airspeed. Those revisions were released on 11 February 2014 and 14 August 2014. This FTD Article was closed with the release of the 14 August 2014 revision. The IAS DISAGREE procedure directs crews to the AIRSPEED UNRELIABLE procedure.

While recently, Boeing has revised the Airspeed Unreliable procedures for 737, 747, 757, 767, 777, and 787 models to incorporate updated industry practice, the FTD Article's reference for addressing erroneous (unreliable) airspeed is accurate.

AAIU Comment:

The AAIU regards the status of this Safety Recommendation as 'Implemented, Closed'.