

<b>Safety Recommendation Number:</b>	IRLD2012007
<b>AAIU Event Reference:</b>	IRL00912062
<b>AAIU Report Number:</b>	2012-019
<b>Date of Publication of Safety Recommendation:</b>	28/11/2012
<b>Safety Recommendation Status:</b>	Implemented, closed

**Safety Recommendation:**

Waterford Airport should provide turn pad guidance lines in accordance with the provisions of Annex 14.

**Response:**

January 2017 -

On 17 January 2017 the AAIU received the following response from the Airport Manager of Waterford Airport;

“I wish to confirm that the corrective action associated with the Safety Recommendation from AAIU Report 2012-019 was completed end of November 2012.

ICAO turning pad surface lines were put in place at both ends of the runway at Waterford Airport.”

**AAIU Comment:**

The AAIU notes the response received and considers that the status of this Safety Recommendation is ‘Implemented, Closed’.