

<b>Safety Recommendation Number:</b>	IRLD2021022
<b>AAIU Event Reference:</b>	IRL00917016
<b>AAIU Report Number:</b>	2021-008
<b>Date of Publication of Safety Recommendation:</b>	5 November 2021
<b>Safety Recommendation Status:</b>	In process of implementation

**Safety Recommendation:**

The Sikorsky Aircraft Corporation should make the necessary updates/modifications to the S-92A helicopter, when configured for SAR operations, to ensure that the active lateral navigation mode information, including AFCS SAR modes, are recorded on the Flight Data Recorder during all flight regimes and mission profiles.

**Response:**

On 22 December 2021, Sikorsky provided the following response to this Safety Recommendation:

"Sikorsky has cataloged and documented this recommendation as SIR-S92A-00257 "SRCH Roll Captured is not Recorded on FDR", and will include this update in the next AMS revision."

**AAIU Comment:**

The AAIU notes the Sikorsky's response of 22 December 2021.

The AAIU considers the status of this Safety Recommendation to be 'In process of implementation'.