

Safety Recommendation Number:	IRLD2013028
AAIU Event Reference:	IRL00912049
AAIU Report Number:	2013-016
Date of Publication of Safety Recommendation:	03/12/2013
Safety Recommendation Status:	Implemented, closed

Safety Recommendation:

Aer Arann should consider qualifying all captains for approaches to RWY 25 at EICK at the earliest opportunity following upgrade.

Response:

Aer Arran advised the AAIU by Email dated 08 November 2013 that:

Aer Arran have published a Flight Crew Instruction (FCI). The FCI amends the Operations Manual removing the requirement for a Short/Narrow Runway qualification, thus removing the restriction on the use of Runway 25 at EICK going forward.

