

Safety Recommendation Number:	IRLD2021023
AAIU Event Reference:	IRL00917016
AAIU Report Number:	2021-008
Date of Publication of Safety Recommendation:	5 November 2021
Safety Recommendation Status:	In process of implementation

Safety Recommendation:

The Sikorsky Aircraft Corporation should make the necessary updates/modifications to the S-92A Helicopter Rotorcraft Flight Manual Supplement No. 4 Part 2, to include a description of the operational usage of the AFCS SAR SRCH mode.

Response:

On 22 December 2021, Sikorsky provided the following response to this Safety Recommendation:

"Sikorsky has cataloged and documented this recommendation as SIR-S92A-00339 "RFMS 04, Part 2 Missing Description of SAR Search Roll Mode". This revision to the RFM will be a part of our next update to Supplement 4 Part 2, which will likely be included in project FCC-114."

AAIU Comment:

The AAIU notes the Sikorsky's response of 22 December 2021.

The AAIU considers the status of this Safety Recommendation to be 'In process of implementation'.